

PACKAGING Guide



max. 30 kg



max. 100 x 100 x 270 cm



no battery





no fluids





no gas




MACHINE IN UPRIGHT POSITION DISPENSE FILLING MATERIAL EVENLY



PUT EVERYTHING CENTERED



EMPTY ALL FLUIDS



SERVICE Process

