



# VIZOR

## Professional / Plus / Air/3



Excellent, unrestricted view of the weld seam



Very comfortable



Individually adjustable darkening

### OPTIONS

/ VIZOR 4000 Professional: Fully automatic levels of protection adapted to the arc within a range of 5 - 13 in automatic mode

/ VIZOR 4000 Plus: Passive levels of protection from 2.5 allow for working in dark rooms (joint preparation and reworking)

/ VIZOR Air/3: Complete air filtration system for protecting the welder's airways



Vizor Air/3

What's your welding challenge?

Let's get connected.